



Intertek

PROGRAM ADMINISTRATOR
DEPARTMENT ALECP
INTERTEK
3933 U.S. ROUTE 11
CORTLAND, NY 13045-0950

ORIGINAL ISSUE DATE: September 28, 2009

Recertification due: January 2015

**An Activity Sponsored and Administered by
Intertek**

LIBERTY AIRPORT SYSTEMS INC
3375 North Service Rd.
Unit C5
Burlington, Ontario
Canada L7N 3G2

**AIRPORT LIGHTING
EQUIPMENT
CERTIFICATION PROGRAM**

**CERTIFICATE OF
CONFORMANCE**

The product described below is hereby approved for listing in the next issue of the Federal Aviation Administration (FAA) Advisory Circular (AC) 150/5345-53, Appendix 3 Addendum "Airport Lighting Equipment Certification Program. The approval is based on successful completion of tests in accordance with the specifications listed in, and the requirements for approval described in the Advisory Circular, and the reporting to the Program Administrator the results of such tests, accompanied by related documents by an Intertek recognized testing laboratory. The certification is not valid for a product modified with non-OEM replacement parts or non-production components.

L-829 – Regulators, Constant Current (AC 150/5345-10F)				
Manufacturer	Rating (kW)	Class	Style	Manufacturer's Catalog Number
Liberty Airport Systems Inc. Lancaster, NY	4	1, 2	1, 2	FSF9X-04XXX-X
	7.5	1, 2	1, 2	FSF9X-07XXX-X
	10	1, 2	1, 2	FSF9X-10XXX-X
	15	1, 2	1, 2	FSF9X-15XXX-X
	20	1, 2	1, 2	FSF9X-20XXX-X
	25	1, 2	1, 2	FSF9X-25XXX-X
	30	1, 2	1, 2	FSF9X-30XXX-X
Air-cooled				

1. This Equipment requires continuing validation in accordance with the requirements of AC 150/5345-53, and the Intertek Airport Lighting Equipment Certification Program.

2. Product tested and Report issued by: Intertek; Kinectrics; Liberty

(A) Report No: 3112382CRT-WIT; 3110654CRT-001; (B) Date of Report: 1/2007; 4/2007; 1/2007; 3110654MIN-002; K-013442-00-1-RC-0001-R00; 45007; 1/2007; 4/2007; 7/2007
72507

NOTE: PLEASE REVIEW, AND ADVISE ADMINISTRATOR AT INTERTEK IMMEDIATELY IF DATA, AS SHOWN, NEED TO BE CORRECTED.

Approved for Certification by:

Jeremy N. Downs, P.E., Program Administrator
Date: September 28, 2009